ARNOLD ENGINEERING 1551 E. Orangethorpe

RECORD OF INSPECTIONS

A - Excellent O - None

B - Good C - Fair

D - Bad

R - Reinspect

* - Eng. Co.

ENGRING

DATE	WIRING	STOCK & STORAGE	TRASH & DISPOSAL	HEAT & EQPT.	FIRE PTCN. EQUIPMENT	INSPECTOR
5-6-76*	ate	ruses bas u	hating being	of ser - 70	NOT TOTAL TROU	3-0
					tents.	100
angueda	talde dru	cylast, re on	enance aupė	inlam , apar	sa blaned le	1/7/78 Me
acids;	EUDITEV 1	avodane bak	e liquids,	combus t f bi	Tlammable and	10
ultrana en	o.td/ plane	DATE (BOLD TO	Tours Series	2110 172 00 10	DO HOU DIE DE	
bnuo	n tengin	s is ablas at	luoda vd ba	y be obtain	Separation ma	
8 9	mo ablir	NI LEISTERE	ON DIE GLER	WIRLL SEV C	and notaryasa	

11/17/75 Don Farmer requested approval for temporary storage & use of one 1 ton container of LIQUID CHLORINE until Fire Department-approved chlorine facility could be finished. Valves are on order, hindering completion of the facility.

The requested cylinder of chlorine would be located at unfinished storage site, plumbed into the building w/ approved lines & fittings. Temporary approval to be for 30 days.

Piercy was advised that approval would be in order if a FFD permit and necessary temporary precautions were met; Piercy to apply for permit if decision is made for this temporary storage. ELH

11:00 A M - CHLORINE Piping test - 312# pressure (manifold); 80# pressure 1/21/76 (vacuum line). Reinspection pending - 24 hours. Don Farmer advised.

Note: Concrete pad, retaining walls, & metal shade roof INSTALLED. ELH

11:00 AM - Reinspection of CHLORINE Piping test: 1/22/76

315# (manifold); 82# (vacuum line)...ACCEPTED.

4/2/76 Reinspection of chlorine storage facility, conducted w/ Don Farmer: Chlorine storage capabilities - Six 1 ton cylinders. Installation has been completed - four 1 ton cylinders are not in place; two are connected to the plant manifolding.

> Recommend that the horizontally-stored cylinders be secured into position by straps, bands, or sufficient means that would eliminate possibility of cylinders rolling & breaking the manifolded plumbing; at the present time, cylinders are positioned between small angle iron blocks, making it possible that cylinder could be bumped while loading or unloading w/ towmotor; an earthquake could be another source of movement to be considered.

CHLORINE NEUTRALIZING MATERIAL - Soda ash is stored near chlorine facility CHLORINE LEAK TEST KIT - located approx. 75' to south, inside building. EMERGENCY CHLORINE REPAIR SERVICE - Phone numbers are posted adjacent to chlorine facility (list of numbers in file-letter of 7/24/75 from Georgia Pacific Corp).

CHLORINE DIFFUSER - Located approx 75' north of chlorine storage; ammonia diffuser was not used as emergency dump to sewer (for chlorine), as intended. An additional diffuser was constructed for this operation. Operational instructions & valve identification NOT posted, as required.

Note: Metal signs were being made by Mtn. Dept. at time of inspection. ELH Reinspection pending.

Permit No. HC 76-43 issued for storage & use of chlorine.

ELH

ELH

8/12/76 Met w/ Don Farmer, maintenance supervisor, re waterflow local gongs not functioning *(arm 3227,8/8/76). Farmer ated he would secure repairs from ADT Service, Los Angeles. **5,000 DBE

8/12/76 Met w/ Don Farmer - SPRINKLER ALARMS have been REPAIRED by ADT; tested in the presence of this Inspector.

12/13/76 Reinspection:

CHLORINE CYLINDERS (Four 1 ton each) - NO CHANGE; cylinders NOT secured from movement, as in 4/2/76 inspection.

CHLORINE DIFFUSER - Valves are NOT identified, as recommended 4/2/76.

Don Farmer not available for inspection. Pending.

1/4/77 CHLORINE DIFFUSER - Has been identified and secured.

3/23/77 Alarm 1275. Faulty thermostat ignited wiring/wood. \$3000 damage to contents.

necessary temporary precautions were met; Piercy to apply for permit 1:

11:00 A M - CHICAINE Piging test - 312# pressure (manifold); 80g pressure

Note: Concrete pac, retaining walls, & metal shade roof INSTALLIN. LIH

11/7/78 Met w/ Donald Farmer, maintenance supervisor, re outside drum storage of flammable and combustible liquids, and carboys of various acids; these are now stored in the same general area, without approved separations.

Separation may be obtained by storing acids at a higher ground elevation than the flammable and combustible liquids, or by a curbing, to prevent exposure or contamination in the event of leakage, spill, or fire.

The need of housekeeping (spills of oils) in this area has been duly noted by the undersigned. Don Farmer was advised of the existing conditions.

Note - Permits to be issued when Don Farmer obtains the quantity and kinds of materials on hand. <u>ELH</u>

11:00 AM - Reinepection of CHLOHINE Piping test: